



;\_bdah[`Y SVZWe[hW`Wee Vg  
S`V ZWSf eZ[W^Xad ekXfZWfUf dgT

>>Q>„f•'“•f'>•„>a††•“

■ \_ ,†f'†"fœf'“>'f'“>•œ>cnbk>•“œ

„†f•'š—>ž•†œ'f,>'•  
cnbk>•“œf•>'†ff'L

- I qPON>†<ž••"f'>•,†f'†"fœf'“>•œ>„•œ†š†  
„••>••'f•K•fžfššfœ'>'“•„••fJ>f'žf•†•šš—>'••œ...š—  
•,†f•f†œ...>'•>††'†f••>,†„„†•“š'>cnbk>'†ff'L
- I qPON>†'>'žf•†•šš—>,f" fš•žf>••>„†fœ—>ž•†œ'fœ†œ>ž•†f•>'†••J  
•,†f'†"fœf'“>„••>'—œ'†f'†>•“œ†f•>œ†fšœ...š•>'†f>œ'f>•žžf•†œ...L  
•†'fœ>†f•'K'††fšš,>f„„f•>•>•fšššL†f>•,†f'†"fœf'“L
- I qPON>†'>••'f•Kœ•'f,>ž•†<f•J>žn••“•'>ž••†šf•  
•žžšš†••'†•œL

Article	: a††•“•••'>••'f•Kœ•'f,>ž•†<f•
Code	: S210
Category	: _••—š†>š•'f->ž•†œ'
End-use	: as the primer/'f•šf•>„••>••'f•K•fžfššfœ'>'—œ urethane surface.
Preparation	: remove thoroughly any oily, salty, iron-rust, or dirty stuff on the surface. Insufficient cleaning may cause peeling-off of the paint later due to loss of adhesiveness.
Coating	: once (standard)
Method	: brush, roller, or spray
Usage	: 150~200 gram/m <sup>2</sup>
Drying	: 30 min to 1 hour in summer, 2~3 hours in winter
Dilution	: •f•,—>'•>'“'f
Tool cleaning	: wash with water or warm water while in wet.
Caution	: Please avoid to coat on soft '—žf>ž•š—"†œ—š>•†š• as it causes breeding by plasticizers.

Package : 10kg/can  
Coating area : 50~66 m<sup>2</sup>



•çÄK¶"½'Á°Ä,¼½...č°,½Ä...ÄÄčč»,'Á

